


PINE LOG ROAD REPAVING



SOLUTION

The project consists of repaving Pine Log Rd from FL 79 to Mullins Rd.

PROBLEM

This collector road has experienced substantial pavement deterioration in many forms: alligator cracking, block cracking, depressions, edge cracking, longitudinal cracking, patching, potholes, and rutting.

